

## FIELD INSPECTION

<b>Project Name:</b>	<b>Mountain Valley Pipeline</b>	<b>Inspector:</b>	<b>Matthew Grant</b>
<b>Inspection Date:</b>	<b>Wednesday, September 26, 2018</b>	<b>Project Contact:</b>	<b>Brian Clauto</b>
<b>Spread: Franklin County</b>	<b>Spread I</b>	<b>Weather (Wet/Dry/Rain):</b>	<b>Wet</b>

**STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Clearing
 ☐ Rough Grading
 ☒ Trench Excavation
 ☒ Pipe Assembly, Testing & Installation  
☒ Backfilling and Grade Restoration
 ☐ Final Grading & Stabilization
 ☐ Other:

- |   |   | Yes                                 | No                                  | N/A                      |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?   | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |


**Comments / Observations:**

- **Area 1** – MP 269 St#14248+55 on going bridge repair.
- **Area 2** - MP 266 St#14059+00 rock check dams require repair & maintenance.
- **Area 3** - MP 266 St#14059+28 sump outlet conveyance channel requires stabilization.

All issues noted for maintenance & stabilization above were added to the daily corrective action punchlist.

**Deadline:** Within 24hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:  Date: 11-5-18

# FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, September 26, 2018

Fig. 1  
MP269 St#1428+55 on going bridge repair



Fig. 2  
MP269 St#1428+55 on going bridge repair



Fig. 3




Fig. 4

